

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FR853
East
> 1
1.160 mi.
6127 ft.

STREET BY NYNEX GARAGE
NEPTUNE AVE BY 12TH ST
BROOKLYN, NY

NY Spills **S103274217**
N/A

Site 2 of 3 in cluster FR

Relative:
Higher

SPILLS:

Actual:
11 ft.

Name: STREET BY NYNEX GARAGE
Address: NEPTUNE AVE BY 12TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9801676 / 1998-06-22
Facility ID: 9801676
Facility Type: ER
DER Facility ID: 257597
Site ID: 319723
DEC Region: 2
Spill Cause: Equipment Failure

Spill Class: Not reported
SWIS: 2401
Spill Date: 1998-05-07
Investigator: MCTIBBE
Referred To: Not reported
Reported to Dept: 1998-05-07
CID: 270
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 1998-05-08
Spill Record Last Update: 2002-05-13
Spiller Name: Not reported
Spiller Company: BELL ATLANTIC
Spiller Address: 1919 NEPTUNE AVE
Spiller Company: 001
Contact Name: HAL DALGIN
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
TIBBE TEMP SPILL # 31. CLEANED BY RP."
Remarks: "(temp spill # 31) broken hose on veh"

All Materials:

Site ID: 319723
Operable Unit ID: 1059570
Operable Unit: 01
Material ID: 323599
Material Code: 0010
Material Name: hydraulic oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 5.00
Units: G
Recovered: .00
Oxygenate: Not reported